

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Site	Standard		Feature	Barrier	Target Completion Date	Completed Date	
Brookdale	1.1	Parking	1.1.1	Compliant Signage	1.1.1.1	FY 2013	
Brookdale	1.1	Parking	1.1.2	Surface	1.1.2.1	FY 2014	
Brookdale	1.1	Parking	1.1.2	Surface	1.1.2.2	FY 2014	
Brookdale	1.1	Parking	1.1.3	Parking Spaces	1.1.3.1	FY 2014	
Brookdale	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.1	FY 2014	
Brookdale	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.2	FY 2014	
Brookdale	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.3	FY 2014	
Brookdale	1.2	Exterior Accessible Route	1.2.3	Transitions	1.2.3.2	Future	
Brookdale	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.1	FY 2013	
Brookdale	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.2	FY 2013	
Brookdale	1.4	Exterior Entry Doors	1.4.1	Maneuvering	1.4.1.1	FY 2013	
Brookdale	1.4	Exterior Entry Doors	1.4.1	Maneuvering	1.4.1.2	FY 2013	
Brookdale	1.4	Exterior Entry Doors	1.4.2	Door Width	1.4.2.1	FY 2013	
Brookdale	1.4	Exterior Entry Doors	1.4.3	Overhead Clearance	1.4.3.2	Leave As Is	
Brookdale	1.4	Exterior Entry Doors	1.4.4	Change in Level	1.4.4.1	FY 2013	
Brookdale	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2013	
Brookdale	1.4	Exterior Entry Doors	1.4.9	Closing Speed	1.4.9.1	FY 2013	
Brookdale	1.5	Elevator/Lift	1.5.6	Auxiliary Power	1.5.6.1	FY 2013	
Brookdale	1.5	Elevator/Lift	1.5.7	Interior Dimension	1.5.7.1	Leave As Is	
Brookdale	1.5	Elevator/Lift	1.6.4	Accessibility Route	1.6.4.1	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.1	Clearance	1.6.1.1	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.1	Clearance	1.6.1.1	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.1	Clearance	1.6.1.1	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.1	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.1	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.1	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.1	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.2	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.3	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.4	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.5	Leave As Is	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.6	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.7	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.1	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.1	Leave As Is	
Brookdale	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.3	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.3	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.1	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.2	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.3	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.4	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.12	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.5	Ramp	1.6.5.1	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.5	Ramp	1.6.5.2	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.5	Ramp	1.6.5.3	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.1	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.2	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.2	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.4	FY 2015	
Brookdale	1.7	Service Counter	1.7.1	Service Counter	1.7.1.3	FY 2013	
Brookdale	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.5	FY 2013	
Brookdale	1.8	Public Spaces	1.8.4	Sink	1.8.1.2	FY 2013	
Brookdale	1.8	Public Spaces	1.8.4	Sink	1.8.1.4	FY 2013	
Brookdale	1.8	Public Spaces	1.8.5	Operating Mechanisms	1.8.5.1	FY 2013	
Brookdale	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
Brookdale	1.9	Employee Offices/Spaces	1.9.5	Clear Floor Space	1.9.5.1	FY 2013	
Brookdale	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
Brookdale	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.2	Leave As Is	
Brookdale	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.2	Leave As Is	
Brookdale	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.2	Leave As Is	
Brookdale	1.11	Restrooms	1.11.1	Compliant Signage	1.11.1.1	FY 2013	
Brookdale	1.11	Restrooms	1.11.1	Compliant Signage	1.11.1.2	FY 2013	
Brookdale	1.11	Restrooms	1.11.2	Mirror	1.11.2.1	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.1	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.3	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.5	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.6	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.8	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.11	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.11	FY 2013	
Brookdale	1.11	Restrooms	1.11.5	Trash Receptacle	1.11.5.1	FY 2013	
Brookdale	1.11	Restrooms	1.11.10	Floor Surface	1.11.10.2	FY 2014	
Brookdale	1.11	Restrooms	1.12.2	Accessibility Route	1.12.2.3	FY 2013	
Brookdale	1.11	Restrooms	1.12.3	Counter/Work Space	1.12.3.2	FY 2013	
Brookdale	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
Brookdale	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.1	FY 2013	
Brookdale	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.3	FY 2013	
Brookdale	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.4	FY 2013	
Brookdale	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.1	FY 2013	
Brookdale	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.2	FY 2013	
Brookdale	1.4	Exterior Entry Doors	1.4.1	Maneuvering Clearance	1.4.1.1	FY 2013	
Brookdale	1.6	Interior Routes/Doors	1.6.4	Accessibility Route	1.6.4.2	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.4	Accessibility Route	1.6.4.3	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.4	Accessibility Route	1.6.4.4	FY 2014	
Brookdale	1.6	Interior Routes/Doors	1.6.5	Ramp	1.6.5.1	FY 2014	
Brookdale	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.5	FY 2013	
Brookdale	1.8	Public Spaces	1.8.5	Operating Mechanisms	1.8.5.1	FY 2013	
Brookdale	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.5.1	FY 2013	
Brookdale	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
Brookdale	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
Brookdale	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.2	Leave As Is	
Brookdale	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.2	Leave As Is	
Brookdale	1.11	Restrooms	1.11.1	Compliant Signage	1.11.1.1	FY 2013	
Brookdale	1.11	Restrooms	1.11.2	Mirror	1.11.2.1	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.1	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.3	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.5	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.6	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.8	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.11	FY 2013	
Brookdale	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.11	FY 2013	
L&F Construction Shop: Pleasant Valley	1.1	Parking	1.1.1	Compliant Signage	1.1.1.11	FY 2013	
L&F Construction Shop: Pleasant Valley	1.1	Parking	1.1.1	Compliant Signage	1.1.1.2	FY 2013	
L&F Construction Shop: Pleasant Valley	1.1	Parking	1.1.1	Compliant Signage	1.1.1.3	FY 2013	
L&F Construction Shop: Pleasant Valley	1.1	Parking	1.1.2	Surface	1.1.2.1	FY 2015	
L&F Construction Shop: Pleasant Valley	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.2	FY 2015	
L&F Construction Shop: Pleasant Valley	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.3	FY 2015	
L&F Construction Shop: Pleasant Valley	1.4	Exterior Entry Doors	1.4.4	Change in Level	1.4.4.1	FY 2015	
L&F Construction Shop: Pleasant Valley	1.4	Exterior Entry Doors	1.4.8	Change in Level	1.4.8.1	FY 2013	
L&F Construction Shop: Pleasant Valley	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
L&F Construction Shop: Pleasant Valley	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
L&F Construction Shop: Pleasant Valley	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
L&F Construction Shop: Pleasant Valley	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
L&F Maintenance Building Winding Creek	1.4	Exterior Entry Doors	1.4.7	Doors	1.4.7.1	FY 2013	
L&F Maintenance Building Winding Creek	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

L&F Mechanics Shop: Rush Creek	1.1	Parking	1.1.3	Parking Spaces	1.1.3.1	FY 2015	
L&F Mechanics Shop: Rush Creek	1.2	Exterior Accessible Route	1.2.5	EAR	1.2.5.1	FY 2015	
L&F Mechanics Shop: Rush Creek	1.4	Exterior Entry Doors	1.4.3	Overhead Clearance	1.4.3.1	FY 2015	
L&F Mechanics Shop: Rush Creek	1.4	Exterior Entry Doors	1.4.7	Doors	1.4.7.1	FY 2015	
L&F Mechanics Shop: Rush Creek	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2015	
L&F Mechanics Shop: Rush Creek	1.4	Closing Speed	1.4.9	Closing Speed	1.4.9.1	FY 2015	
L&F Mechanics Shop: Rush Creek	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
L&F Mechanics Shop: Rush Creek	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
L&F Mechanics Shop: Rush Creek	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
L&F Mechanics Shop: Rush Creek	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
L&F Region 1 Shop: Glacial Park	1.1	Parking	1.1.3	Parking Spaces	1.1.3.1	FY 2015	
L&F Region 1 Shop: Glacial Park	1.2	Exterior Accessible Route	1.2.5	Exterior Accessible Route	1.2.5.1	FY 2015	
L&F Region 1 Shop: Glacial Park	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
L&F Region 1 Shop: Glacial Park	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
L&F Region 1 Shop: Glacial Park	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.2	Leave As Is	
L&F Region 2 Shop: Rush Creek	1.1	Parking	1.1.3	Parking Spaces	1.1.3.1	FY 2015	
L&F Region 2 Shop: Rush Creek	1.2	Exterior Accessible Route	1.2.5	EAR	1.2.5.1	FY 2015	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

L&F Region 2 Shop: Rush Creek	1.4	Exterior Entry Doors	1.4.4	Change in Level	1.4.4.1	FY 2015	
L&F Region 2 Shop: Rush Creek	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2015	
L&F Region 2 Shop: Rush Creek	1.6	Interior Routes/Doors	1.6.1	Clearance	1.6.1.3	FY 2013	
L&F Region 2 Shop: Rush Creek	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.4	FY 2013	
L&F Region 2 Shop: Rush Creek	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.5	FY 2013	
L&F Region 2 Shop: Rush Creek	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
L&F Region 2 Shop: Rush Creek	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
L&F Region 2 Shop: Rush Creek	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
L&F Region 2 Shop: Rush Creek	1.9	Employee Offices/Spaces	1.11.9	Leave As Is - 2010 Standards 106.5	1.11.9.1	Leave As Is	
L&F Region 2 Shop: Rush Creek	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
L&F Region 3 Shop: Coral Woods	1.1	Parking	1.1.1	Compliant Signage	1.1.1.1	FY 2013	
L&F Region 3 Shop: Coral Woods	1.1	Parking	1.1.1	Compliant Signage	1.1.1.2	FY 2013	
L&F Region 3 Shop: Coral Woods	1.1	Parking	1.1.1	Compliant Signage	1.1.1.3	FY 2013	
L&F Region 3 Shop: Coral Woods	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.2	FY 2015	
L&F Region 3 Shop: Coral Woods	1.4	Exterior Entry Doors	1.4.4	Change in Level	1.4.4.1	FY 2015	
L&F Region 3 Shop: Coral Woods	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1	FY 2013	
L&F Region 3 Shop: Coral Woods	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

L&F Region 3 Shop: Coral Woods	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8	Leave As Is	
L&F Region 3 Shop: Coral Woods	1.11	Restrooms	1.11.9	Leave As Is - 2010 Standards 106.5	1.11.9.1	Leave As Is	
L&F Region 3 Shop: Coral Woods	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
L&F Region 4 Shop: Fel Pro RRR	1.1	Parking	1.1.3	Parking Spaces	1.1.3.1	FY 2015	
L&F Region 4 Shop: Fel Pro RRR	1.1	Parking	1.1.4.2	Transitions	1.1.4.2	FY 2015	
L&F Region 4 Shop: Fel Pro RRR	1.2	Exterior Accessible Route	1.2.5	EAR	1.2.5.1	FY 2015	
L&F Region 4 Shop: Fel Pro RRR	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2013	
L&F Region 4 Shop: Fel Pro RRR	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.4.4.1	FY 2015	
L&F Region 4 Shop: Fel Pro RRR	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
L&F Region 4 Shop: Fel Pro RRR	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
L&F Region 4 Shop: Fel Pro RRR	1.11	Restrooms	1.11.9	Leave As Is - 2010 Standards 106.5	1.11.9.1	Leave As Is	
L&F Region 4 Shop: Fel Pro RRR	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
L&F Region 5 Shop: Stickney Run	1.1	Parking	1.1.3	Parking Spaces	1.1.3.1	FY 2015	
L&F Region 5 Shop: Stickney Run	1.2	Exterior Accessible Route	1.2.5	EAR	1.2.5.1	FY 2015	
L&F Region 5 Shop: Stickney Run	1.4	Exterior Entry Signage	1.4.4	Change in Level	1.4.4.1	FY 2015	
L&F Region 5 Shop: Stickney Run	1.4	Exterior Entry Doors	1.4.5	Threshold	1.4.5.1	FY 2015	
L&F Region 5 Shop: Stickney Run	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

L&F Region 5 Shop: Stickney Run	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
L&F Region 5 Shop: Stickney Run	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
L&F Region 5 Shop: Stickney Run	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
L&F Region 5 Shop: Stickney Run	1.11	Restrooms	1.11.9	Leave As Is - 2010 Standards 106.5	1.11.9.1	Leave As Is	
L&F Region 5 Shop: Stickney Run	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
L&F Region 6 Shop: Prairieview	1.1	Parking	1.1.3	Parking Spaces	1.1.3.1	FY 2015	
L&F Region 6 Shop: Prairieview	1.1	Parking	1.1.4	Transitions	1.1.4.2	FY 2015	
L&F Region 6 Shop: Prairieview	1.2	Exterior Accessible Route	1.2.5	EAR	1.2.5.1	FY 2015	
L&F Region 6 Shop: Prairieview	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2013	
L&F Region 6 Shop: Prairieview	1.4	Exterior Entry Doors	1.4.9	Closing Speed	1.4.9.1	FY 2013	
L&F Region 6 Shop: Prairieview	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
L&F Region 6 Shop: Prairieview	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
L&F Region 6 Shop: Prairieview	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
L&F Region 6 Shop: Prairieview	1.11	Restrooms	1.11.9	Leave As Is - 2010 Standards 106.5	1.11.9.1	Leave As Is	
L&F Region 6 Shop: Prairieview	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
Lost Valley Visitor Center	1.1	Parking	1.1.1	Parking	1.1.1.1	FY 2013	
Lost Valley Visitor Center	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.6	FY 2013	
Lost Valley Visitor Center	1.4	Parking	1.4.8	LBF	1.4.8.1	FY 2013	
Lost Valley Visitor Center	1.4	Exterior Entry Doors	1.4.9	Closing Speed	1.4.9.1	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Lost Valley Visitor Center	1.5	Elevator/Lift	1.5.4	Timing	1.5.4.1	FY 2013	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.1	Maneuvering/Overhead Clearance	1.6.1.1	FY 2013	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.1	Maneuvering/Overhead Clearance	1.6.1.2	FY 2014	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.1	FY 2013	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.3	FY 2013	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.4	FY 2013	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.5	FY 2013	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.6	FUTURE	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.1	FY 2014	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.2	FY 2014	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.3	FY 2014	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.1	FY 2013	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.2	FY 2013	
Lost Valley Visitor Center	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.5	FY 2013	
Lost Valley Visitor Center	1.7	Service Counter	1.7.1	Service Counter	1.7.1.1	FY 2013	
Lost Valley Visitor Center	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.1	FY 2013	
Lost Valley Visitor Center	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.3	FY 2013	
Lost Valley Visitor Center	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.4	FY 2013	
Lost Valley Visitor Center	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.5	FY 2013	
Lost Valley Visitor Center	1.8	Public Spaces	1.8.4	Sink	1.8.4.4	TBD	
Lost Valley Visitor Center	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
Lost Valley Visitor Center	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
Lost Valley Visitor Center	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
Lost Valley Visitor Center	1.11	Restrooms	1.11.2	Mirror	1.11.2.4	Leave As Is	
Lost Valley Visitor Center	1.11	Restrooms	1.11.3	Sink	1.11.3.1	Leave As Is	
Lost Valley Visitor Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.3	Leave As Is	
Lost Valley Visitor Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.8	FY 2013	
Lost Valley Visitor Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.3	Leave As Is	
Lost Valley Visitor Center	1.12	Kitchen	1.12.2	Accessibility Route	1.11.2.1	Leave As Is	
Lost Valley Visitor Center	1.12	Kitchen	1.12.4	Sink	1.12.4.2	Leave As Is	
Lost Valley Visitor Center	1.12	Kitchen	1.12.8	Leave As Is - 2010 Standards 106.5	1.12.8.1	Leave As Is	
Lost Valley Visitor Center	1.13	Locker Rooms	1.13.1	Compliant Signage	1.13.1.1	FY 2013	
Lost Valley Visitor Center	1.13	Locker Rooms	1.13.2	Accessibility Route	1.13.2.1	FY 2013	
Lost Valley Visitor Center	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Lost Valley Visitor Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.1	FY 2013	
Lost Valley Visitor Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.3	FY 2013	
Lost Valley Visitor Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.4	FY 2013	
NRM North Facility: Glacial Park	1.1	Parking	1.1.1	Compliant Signage	1.1.1.1	FY 2013	
NRM North Facility: Glacial Park	1.1	Parking	1.1.1	Compliant Signage	1.1.1.2	FY 2013	
NRM North Facility: Glacial Park	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.1	FY 2015	
NRM North Facility: Glacial Park	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.1	FY 2015	
NRM North Facility: Glacial Park	1.4	Exterior Entry Doors	1.4.4	Change in Level	1.4.4.1	FY 2015	
NRM North Facility: Glacial Park	1.4	Exterior Entry Doors	1.4.6	Gaps	1.4.6.1	FY 2015	
NRM North Facility: Glacial Park	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2013	
NRM North Facility: Glacial Park	1.6	Interior Routes/Doors	1.6.1	Maneuvering/Overhead Clearance	1.6.1.1	FY 2013	
NRM North Facility: Glacial Park	1.6	Interior Routes/Doors	1.6.1	Maneuvering/Overhead Clearance	1.6.1.2	FY 2015	
NRM North Facility: Glacial Park	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.3	FY 2013	
NRM North Facility: Glacial Park	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.4	FY 2013	
NRM North Facility: Glacial Park	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.5	FY 2013	
NRM North Facility: Glacial Park	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
NRM North Facility: Glacial Park	1.11	Restrooms	1.11.9	Leave As Is - 2010 Standards 106.5	1.11.9.1	Leave As Is	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

NRM North Facility: Glacial Park	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
NRM South Facility: Pleasant Valley	1.1	Parking	1.1.3	Parking Spaces	1.1.3.1	FY 2013	
NRM South Facility: Pleasant Valley	1.1	Parking	1.1.4	Transitions	1.1.4.2	FY 2015	
NRM South Facility: Pleasant Valley	1.1	Parking	1.1.5	Entire Parking Lot	1.1.5.1	FY 2015	
NRM South Facility: Pleasant Valley	1.2	Exterior Accessible Route	1.2.5	EAR	1.2.5.1	FY 2015	
NRM South Facility: Pleasant Valley	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.1	FY 2013	
NRM South Facility: Pleasant Valley	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.2	FY 2013	
NRM South Facility: Pleasant Valley	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2013	
NRM South Facility: Pleasant Valley	1.4	Exterior Entry Doors	1.4.9	Closing Speed	1.4.9.1	FY 2013	
NRM South Facility: Pleasant Valley	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.4	FY 2013	
NRM South Facility: Pleasant Valley	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.5	FY 2013	
NRM South Facility: Pleasant Valley	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.4	FY 2013	
NRM South Facility: Pleasant Valley	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.5	FY 2013	
NRM South Facility: Pleasant Valley	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
NRM South Facility: Pleasant Valley	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
NRM South Facility: Pleasant Valley	1.9	Employee Offices/Spaces	1.9.3	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
NRM South Facility: Pleasant Valley	1.11	Restrooms	1.11.1	Compliant Signage	1.11.1.1	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

NRM South Facility: Pleasant Valley	1.11	Restrooms	1.11.3	Sink	1.11.3.1	FY 2013	
NRM South Facility: Pleasant Valley	1.11	Restrooms	1.11.3	Sink	1.11.3.5	FY 2013	
NRM South Facility: Pleasant Valley	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.1	FY 2013	
NRM South Facility: Pleasant Valley	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.3	FY 2013	
NRM South Facility: Pleasant Valley	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.4	FY 2013	
NRM South Facility: Pleasant Valley	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.7	FY 2013	
NRM South Facility: Pleasant Valley	1.11	Restrooms	1.11.7	Circulation	1.11.7.1	FY 2013	
NRM South Facility: Pleasant Valley	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
NRM South Facility: Pleasant Valley	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.1	Future	
NRM South Facility: Pleasant Valley	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.3	Future	
NRM South Facility: Pleasant Valley	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.4	Future	
Police Shop: LVVC	1.3	Exterior Signage	1.3.1	Entry Signage	1.3.1.1	FY 2013	
Police Shop: LVVC	1.4	Exterior Entry Doors	1.4.7	Doors	1.4.7.2	FY 2015	
Police Shop: LVVC	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
Police Shop: LVVC	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
Police Shop: LVVC	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
Police Shop: LVVC	1.11	Restrooms	1.11.9	Leave As Is - 2010 Standards 106.5	1.11.9.1	Leave As Is	
Police Shop: LVVC	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	Future	
Prairieview Education Center	1.1	Parking	1.1.1	Compliant Signage	1.1.1.1	FY 2013	
Prairieview Education Center	1.1	Parking	1.1.1	Compliant Signage	1.1.1.2	FY 2013	
Prairieview Education Center	1.1	Parking	1.1.2	Surface	1.1.2.1	FY 2013	
Prairieview Education Center	1.1	Parking	1.1.2	Surface	1.1.2.2	FY 2013	
Prairieview Education Center	1.1	Parking	1.1.3	Parking Spaces	1.1.3.1	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Prairieview Education Center	1.1	Parking	1.1.3	Parking Spaces	1.1.3.2	FY 2013	
Prairieview Education Center	1.1	Parking	1.1.4	Transitions	1.1.4.1	FY 2013	
Prairieview Education Center	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.6	FY 2013	
Prairieview Education Center	1.2	Exterior Accessible Route	1.2.2	Clearance	1.2.2.3	FY 2014	
Prairieview Education Center	1.2	Exterior Accessible Route	1.2.3	Transitions	1.2.3.1	FY 2013	
Prairieview Education Center	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.1	FY 2013	
Prairieview Education Center	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.2	FY 2013	
Prairieview Education Center	1.4	Exterior Entry Doors	1.4.4	Change in Level	1.4.4.1	FY 2014	
Prairieview Education Center	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2013	
Prairieview Education Center	1.4	Exterior Entry Doors	1.4.9	Closing Speed	1.4.9.1	FY 2013	
Prairieview Education Center	1.5	Elevator/Lift	1.5.5	Floor Surface	1.5.5.1	FY 2014	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.1	Interior Accessible Route	1.6.1.1	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.1	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.2	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.3	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.4	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.5	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.6	FY 2014	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.1	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.2	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.3	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.11	FY 2014	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.1	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.2	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.2	FY 2013	
Prairieview Education Center	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.6	Leave As Is	
Prairieview Education Center	1.7	Service Counter	1.7.1	Service Counter	1.7.1.1	FY 2014	
Prairieview Education Center	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.1	FY 2013	
Prairieview Education Center	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.3	FY 2013	
Prairieview Education Center	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.4	FY 2013	
Prairieview Education Center	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.5	FY 2013	
Prairieview Education Center	1.8	Public Spaces	1.8.2	Floor Surface	1.8.2.1	FY 2013	
Prairieview Education Center	1.8	Public Spaces	1.8.3	Work Surface	1.8.3.1	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Prairieview Education Center	1.8	Public Spaces	1.8.5	Operating Mechanisms	1.8.5.1	FY 2013	
Prairieview Education Center	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
Prairieview Education Center	1.9	Employee Offices/Spaces	1.9.2	60" Turnng Space	1.9.2.1	FY 2013	
Prairieview Education Center	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.1	Leave As Is	
Prairieview Education Center	1.11	Restrooms	1.11.1	Compliant Signage	1.11.1.1	FY 2013	
Prairieview Education Center	1.11	Restrooms	1.11.2	Mirror	1.11.2.4	FY 2013	
Prairieview Education Center	1.11	Restrooms	1.11.3	Sink	1.11.3.8	FY 2013	
Prairieview Education Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.1	FY 2014	
Prairieview Education Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.3	Leave As Is	
Prairieview Education Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.4	FY 2014	
Prairieview Education Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.5	Leave As Is	
Prairieview Education Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.6	Leave As Is	
Prairieview Education Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.7	FY 2013	
Prairieview Education Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.8	FY 2013	
Prairieview Education Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.11	FY 2013	
Prairieview Education Center	1.12	Kitchen	1.12.2	Accessibility Route	1.12.2.1	FY 2013	
Prairieview Education Center	1.12	Kitchen	1.12.4	Sink	1.12.4.2	Leave As Is	
Prairieview Education Center	1.12	Kitchen	1.12.8	Leave As Is - 2010 Standards 106.5	1.12.8.1	Leave As Is	
Prairieview Education Center	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.2	FY 2015	
Prairieview Education Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.1	FY 2013	
Prairieview Education Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.3	FY 2013	
Prairieview Education Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.4	FY 2013	
Prairieview Education Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.5	FY 2013	
Prairieview Education Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.6	FY 2013	
Research Field Station	1.1	Parking		Determine Facility Use		TBD	
Research Field Station	1.2	Exterior Accessible Route		Determine Facility Use		TBD	
Research Field Station	1.3	Exterior Signage		Determine Facility Use		TBD	
Research Field Station	1.4	Exterior Entry Doors		Determine Facility Use		TBD	
Research Field Station	1.6	Interior Routes/Doors		Determine Facility Use		TBD	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Research Field Station	1.7	Service Counter		Determine Facility Use		TBD	
Research Field Station	1.8	Public Spaces		Determine Facility Use		TBD	
Research Field Station	1.9	Employee Offices/Spaces		Determine Facility Use		TBD	
Research Field Station	1.11	Restrooms		Determine Facility Use		TBD	
Research Field Station	1.14	Aural and Visual Alarms		Determine Facility Use		TBD	
Research Field Station	1.15	Directional & Permanent Signs		Determine Facility Use		TBD	
Weidrich Barn	1.1	Parking	1.1.1	Compliant Signage	1.1.1.1	FY 2013	
Weidrich Barn	1.1	Parking	1.1.1	Compliant Signage	1.1.1.2/3	FY 2013	
Weidrich Barn	1.1	Parking	1.1.3	Parking Spaces	1.1.2.3	FY 2014	
Weidrich Barn	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.1	FY 2013	
Weidrich Barn	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.2	FY 2013	
Weidrich Barn	1.4	Exterior Entry Doors	1.4.1	Maneuvering Clearance	1.4.1.1	FY 2013	
Weidrich Barn	1.4	Exterior Entry Doors	1.4.3	Overhead Clearance	1.4.3.1	FY 2015	
Weidrich Barn	1.4	Exterior Entry Doors	1.4.4	Change in Level	1.4.4.1	FY 2015	
Weidrich Barn	1.4	Exterior Entry Doors	1.4.5	Threshold	1.4.5.1	FY 2015	
Weidrich Barn	1.4	Exterior Entry Doors	1.4.6	Gaps	1.4.6.1	FY 2015	
Weidrich Barn	1.4	Exterior Entry Doors	1.4.7	Hardware	1.4.7.2	FY 2015	
Weidrich Barn	1.4	Exterior Entry Doors	1.4.8	LBF	1.4.8.1	FY 2013	
Weidrich Barn	1.4	Exterior Entry Doors	1.4.9	Closing Speed	1.4.9.1	FY 2013	
Weidrich Barn	1.4	Exterior Entry Doors	1.4.10	Series of Doors Closer	1.4.10.1	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.1	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.2	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.3	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.4	FY 2013	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.5	FY 2013	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.7	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.8	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.2	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.3	Floor Surface	1.6.3.3	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.1	FY 2013	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.4	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.11	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.16	Future	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Weidrich Barn	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.1	FY 2015	
Weidrich Barn	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.2	FY 2015	
Weidrich Barn	1.7	Service Counter	1.7.1	Service Counter	1.7.1.1	FY 2015	
Weidrich Barn	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.1	FY 2013	
Weidrich Barn	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.2	FY 2013	
Weidrich Barn	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.4	FY 2013	
Weidrich Barn	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.5	FY 2013	
Weidrich Barn	1.8	Public Spaces	1.8.1	Accessibility Route	1.8.1.6	Leave As Is	
Weidrich Barn	1.8	Public Spaces	1.8.2	Accessibility Route	1.8.2.2	FY 2015	
Weidrich Barn	1.8	Public Spaces	1.8.2	Accessibility Route	1.8.2.3	FY 2015	
Weidrich Barn	1.8	Public Spaces	1.8.2	Accessibility Route	1.8.2.4	FY 2015	
Weidrich Barn	1.8	Public Spaces	1.8.3	Accessibility Route	1.8.3.1	FY 2015	
Weidrich Barn	1.8	Public Spaces	1.8.3	Accessibility Route	1.8.3.2	FY 2015	
Weidrich Barn	1.8	Public Spaces	1.8.4	Accessibility Route	1.8.4.2/4	FY 2015	
Weidrich Barn	1.9	Public Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.2	Leave As Is	
Weidrich Barn	1.11	Restrooms	1.11.1	Compliant Signage	1.11.1.1	FY 2013	
Weidrich Barn	1.11	Restrooms	1.11.2	Mirror	1.11.2.1	FY 2013	
Weidrich Barn	1.11	Restrooms	1.11.3	Sink	1.11.3.3	FY 2014	
Weidrich Barn	1.11	Restrooms	1.11.3	Sink	1.11.3.5	FY 2014	
Weidrich Barn	1.11	Restrooms	1.11.3	Sink	1.11.3.6	FY 2014	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.1	FY 2014	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.4	FY 2014	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.5	FY 2013	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.6	FY 2013	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.7	FY 2013	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.8	FY 2013	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.10	FY 2014	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.11	FY 2014	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.12	FY 2014	
Weidrich Barn	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.13	FY 2014	
Weidrich Barn	1.12	Kitchen	1.12.4	Sink	1.12.4.2/4	FY 2015	
Weidrich Barn	1.12	Kitchen	1.12.5	Oven	1.12.5.1	FY 2015	
Weidrich Barn	1.12	Kitchen	1.12.7	Storage	1.12.7.1	FY 2015	
Weidrich Barn	1.12	Kitchen	1.12.8	Leave As Is - 2010 Standards 106.5	1.12.8.1	Leave As Is	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Weidrich Barn	1.14	Aural and Visual Alarms	1.14.1.	Audible and Visual Alarms	1.14.1.2	Future	
Weidrich Barn	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.3	FY 2013	
Wildlife Resource Center	1.1	Parking	1.1.1	Compliant Signage	1.1.1.2	FY 2013	
Wildlife Resource Center	1.1	Parking	1.1.2	Surface	1.1.2.1	FY 2015	
Wildlife Resource Center	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.4	FY 2015	
Wildlife Resource Center	1.2	Exterior Accessible Route	1.2.1	Surface	1.2.1.5	FY 2015	
Wildlife Resource Center	1.2	Exterior Accessible Route	1.2.6	Ramps	1.2.6.1	FY 2015	
Wildlife Resource Center	1.2	Exterior Accessible Route	1.2.6	Ramps	1.2.6.2	FY 2015	
Wildlife Resource Center	1.2	Exterior Accessible Route	1.2.6	Ramps	1.2.6.3	FY 2015	
Wildlife Resource Center	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.1	FY 2013	
Wildlife Resource Center	1.3	Exterior Entry Signage	1.3.1	Entry Signage	1.3.1.2	FY 2013	
Wildlife Resource Center	1.4	Exterior Entry Doors	1.4.4	Change in Level	1.4.4.1	FY 2014	
Wildlife Resource Center	1.6	Interior Routes/Doors	1.6.1	Clearance	1.6.1.1	FY 2013	
Wildlife Resource Center	1.6	Interior Routes/Doors	1.6.1	Clearance	1.6.1.2	FY 2013	
Wildlife Resource Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.3	FY 2013	
Wildlife Resource Center	1.6	Interior Routes/Doors	1.6.2	Interior Doors	1.6.2.5	FY 2013	
Wildlife Resource Center	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.7	FY 2013	
Wildlife Resource Center	1.6	Interior Routes/Doors	1.6.4	Interior Routes	1.6.4.16	FY 2014	
Wildlife Resource Center	1.6	Interior Routes/Doors	1.6.6	Stairs	1.6.6.6	Leave As Is	
Wildlife Resource Center	1.9	Employee Offices/Spaces	1.9.1	36" Access Aisle	1.9.1.1	FY 2013	
Wildlife Resource Center	1.9	Employee Offices/Spaces	1.9.2	60" Turning Space	1.9.2.1	FY 2013	
Wildlife Resource Center	1.9	Employee Offices/Spaces	1.9.4	Protruding Objects	1.9.4.1	Leave As Is	
Wildlife Resource Center	1.9	Employee Offices/Spaces	1.9.5	Clear Floor Space	1.9.5.1	Leave As Is	
Wildlife Resource Center	1.9	Employee Offices/Spaces	1.9.6	Reach Range	1.9.6.1	Leave As Is	
Wildlife Resource Center	1.9	Employee Offices/Spaces	1.9.8	Leave As Is - 2010 Standards 106.5	1.9.8.2	Leave As Is	
Wildlife Resource Center	1.11	Restrooms	1.11.1	Compliant Signage	1.11.1.1	FY 2013	
Wildlife Resource Center	1.11	Restrooms	1.11.2	Mirror	1.11.2.1	FY 2013	
Wildlife Resource Center	1.11	Restrooms	1.11.3	Sink	1.11.3.5	FY 2013	
Wildlife Resource Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.1	FY 2013	
Wildlife Resource Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.3	FY 2013	
Wildlife Resource Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.6	FY 2013	
Wildlife Resource Center	1.11	Restrooms	1.11.4	Toilet/Urinals	1.11.4.7	FY 2013	

ADA System-Wide Site Facility Audit Transition Plan - FACILITIES

Wildlife Resource Center	1.12	Kitchen	1.12.2	Accessibility Route	1.12.2.4	Leave As Is	
Wildlife Resource Center	1.12	Kitchen	1.12.2	Accessibility Route	1.12.2.5	Leave As Is	
Wildlife Resource Center	1.12	Kitchen	1.12.4	Sink	1.12.4.2	Leave As Is	
Wildlife Resource Center	1.14	Aural and Visual Alarms	1.14.1	Audible and Visual Alarms	1.14.1.1	FY 2014	
Wildlife Resource Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.1	FY 2013	
Wildlife Resource Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.3	FY 2013	
Wildlife Resource Center	1.15	Directional & Permanent Signs	1.15.1	Compliant Signage	1.15.1.4	FY 2013	